



26.6.20.1408 CTW Probe©

June 20, 2026 – Release

Feature Additions –

- * ** Feature 4956 ** Add "Set Current Limit" Command
- * ** Feature 4965 ** Validation Command - built into a Test sequence
- * ** Feature 4969 ** Force Control
- * ** User Story 4366 ** CDC software to Test valve response
- * ** User Story 4972 ** RD - Recognize STO Signal and Gray Out Test Button
- * ** User Story 4978 ** Support A1 Additional IO
- * ** User Story 4985 ** Add A3200 Multicard V2 Option With Real Current Channels
- * ** User Story 4992 ** Add Non-Key Based Licensing
- * ** User Story 4999 ** Update CDC For Customer Requests

Enhancements

- * ** Feature 4942 ** Add "Analog Control" to Task 5 in Motion composer
- * ** Feature 4983 ** Test Builder - Maximum Travel Exceeded Message
- * ** User Story 4928 ** Splash Screen Improvement

Bug Fixes –

- * ** Bug 4870 ** Test Builder Command Parameters Selection ambiguity
- * ** Bug 4946 ** No splash screen for most of program boot up
- * ** Bug 4968 ** Roehrig import units issue
- * ** Bug 4973 ** OutOfMem exception on File Load for Misconfigured Machine
- * ** Bug 4976 ** "Export All Runs" Fails if Two Runs Have Same Description
- * ** Bug 4988 ** System.InvalidOperationException from Legend
- * ** Bug 4989 ** System.ArgumentException when trying to load shock data on spring

Other

- * ** Bug 4990 ** Error 153 on Help Page
- * ** Bug 4993 ** Probe Crash When No Units On Velocity Sensor
- * ** Bug 4994 ** Strange Errors on File Load if Force Channel Not Named Correctly
- * ** Bug 4996 ** LiveView Channels List Sometimes Wrong on Single Card LAs
- * ** Bug 4998 ** Error when opening REI data
- * ** Bug 5000 ** Machine Extension Page Gives Certificate Error